Parts List for CNC Router 3-4 MDF Parts - b.txt

Part#	Dimensions	Name
1)	6 x 8 7/8	Z Axis Platform
2)	6 x 3 1/8	Z Axis Bearing Support
3)	6 x 3 1/8	Z Axis Bearing Support
4)	6 x 2	Z Axis Router Clamp Base
5)	6 x 2	Z Axis Router Clamp Base
6)	2 x 4 1/4	Z Axis Router Clamp
7)	2 x 4 1/4	Z Axis Router Clamp
8)	7 1/2 x 13 3/4	X Axis Platform
9)	7 1/2 x 2 3/4	X Axis Top Plate
10)	7 1/2 x 2 3/4	X Axis Bottom Plate
11)	7 1/2 x 3 1/4	X Axis Bearing Mount
12)	7 1/2 x 3 1/4	X Axis Bearing Mount
13)	5 1/4 x 3 1/4	X Axis Nut Support
14)	2 x 2	Small Adjustment Block
15)	2 x 2	Small Adjustment Block
16)	2 x 2	Small Adjustment Block
17)	2 x 2	Small Adjustment Block
18)	2 x 2	Small Adjustment Block
19)	2 x 2	Small Adjustment Block
20)	2 x 2	Small Adjustment Block
21)	2 x 2	Small Adjustment Block
22)	21 1/2 x 8	Gantry Side - Right
23)	21 1/2 x 8	Gantry Side - Left
24)	23 x 8	Gantry Bottom
25)	23 x 10 1/2	Gantry Rear Brace
26)	24 1/2 x 2 7/8	Gantry Front
27)	8 x 1 1/2	Gantry Corner Block
28)	8 x 1 1/2	Gantry Corner Block
29)	8 x 3	Y Axis Bearing Block
30)	8 x 3	Y Axis Bearing Block
31)	8 1/4 x 32 1/2	Support - Motor Side
32)	8 1/4 x 32 1/2	Support - Motor Side
33)	8 1/4 x 32 1/2	Support - Bearing Side
34)	8 1/4 x 32 1/2	Support - Bearing Side
35)	2 1/2 x 2 1/2	Adjustment Block Large
36)	2 1/2 x 2 1/2	Adjustment Block Large
37)	2 1/2 x 2 1/2	Adjustment Block Large
38)	2 1/2 x 2 1/2	Adjustment Block Large
39)	43 1/2 x 22	Cutting Bed

Cutting Diagram for CNC Router 3-4 MDF Parts - b.txt

Supply piece 1



Supply piece 2